## Drying of Milk **LPT-610** UNIT - I

By: Dr. Gargi Mahapatra, Assistant Professor cum Junior Scientist **Department of Livestock Products Technology Bihar Veterinary College Bihar Animal Sciences University, Patna-14.** 

## **Dried Product**

Products which when recombined with water gives little or no evidence of detrimental changes when compared to the original/liquid product.

Purpose: Utilisation of product in flush season; consistent supply in the lean season and price maintenance throughout the year.





## Why the need to dry milk? (aim/objective)

- Increase shelf-life and stability of the product.
- Proper utilisation of the product during flush season.
- Maintain product cost throughout the year.
- Ease storage and transport.
- Increase usage based on versatiliy.

## **Dried Milk**

Product obtained from by removing water/moisture from milk by heat or other suitable means, to produce a solid containing 5% moisture or less.

• Dried Whole Milk or Whole Milk Powder (WMP)

Dried Skim Milk or Skim Milk
Powder (SMP) or Non-Fat Dry Milk
(NFDM)



## **Dried Mik Definition(PFA Rules, 1976)**

- dried and 2.0 for a spray dried product.
- packed in hermetically sealed containers when the quantity exceeds 510/gm.

• WMP- It is the product obtained from cow or buffalo milk or a combination thereof or from standardised milk, by the removal of water. It may contain calcium chloride, citric acid and sodium citrate, sodium salts of ortho-phosphoric and poly-phosphoric acids, not exceeding 0.3% by weight of the finished product and 0.01% of butylated hydroxy anisole by weight of the finished product. Such additions need to be declared on the label. Milk powder should not contain more than 5.0% of moisture and not less than 26.0% fat. The total acidity expressed as lactic acid should not be more than 1.2%. The standard plate count may not exceed 50,000/gm and the coliform count may not exceed 90/gm. The solubility index should be 15.0 for a roller

• Note: Process of drying should be mentioned on the label and spray dried product should be




## **Dried Mik Definition(PFA Rules, 1976)**

- should be 15.0 for a roller dried and 2.0 for a spray dried product.
- packed in hermetically sealed containers when the quantity exceeds 510/gm.

• SMP- It is the product obtained from skim milk of cow or buffalo or a combination thereof of by the removal of water. It may contain calcium chloride, citric acid and sodium citrate, sodium salts of ortho-phosphoric and poly-phosphoric acids, not exceeding 0.3% by weight of the finished product. Such additions need to be declared on the label. Skim milk powder should not contain more than 5.0% of moisture and not more than 1.50% milk fat. The total acidity expressed as lactic acid should not be more than 1.5%. The standard plate count may not exceed 50,000/gm and the coliform count may not exceed 90/gm. The solubility index

• Note: Process of drying should be mentioned on the label and spray dried product should be





## Freezing of Milk and Sublimation **Steps**

Step 1: Freezing the product.

Step 2: Supplying heat to remove moisture by sublimation.

## Film, Roller or Drum Drying Principle

A thin film of concentrated milk is applied upon the smooth surface of a application of the milk. The thin film of milk is then ground to obtain powder. Types: Single Drum, Twin drum and Double Drum & Atmospheric/Vacuum steel.

Most commonly used :- Cast Iron & Double drum atmospheric drier

- continuously rotating steam heated metal drum and the thin film of dried milk is continuously scrapped off by a stationary knife located opposite to the point of
- Materials used: Steel; Alloy Steel; Stainless steel; Cast Iron; Chrome and Nickel Plated



## Spray Drying **Compressed Air, Pressure Spray and Centrifugal Disc**

fine powder. This is then removed continuously. microns.

- Principle: Atomizing the pre-heated and concentrated milk to form a spray of very minute droplets, like a fog or mist. These droplets are then directed into a very large, suitably designed drying chamber where they come in contact with currents of hot air. Due to high temperature and large surface area the milk particles evaporate their moisture almost instantaneously and transform into a
- Note: The process of atomisation reduces the particle size to a range of 50-150



## 

Other than drying whole milk and skim milk, this process is mainly applied to dry milk products and by-products such as butter milk, Cream (sweet and sour), whey and emulsified cheese slurry. This is done by forcing gas into the liquid product after pump but before the atomiser .

Note: Air is commonly used as the added gas for making foam spray non-fat dry milk and nitrogen is used as added gas for making foam spray dried whole milk. Particles of the dried product obtained by foam spray drying are more uniform in size

# R

# Instantiation Agglomeration

**Definition, Principle and Purpose** 

## Thank You

### Dr. Gargi Mahapatra